

Fig. 1




Fig. 2




Fig. 3




Fig. 4

Fig. 4 is a detailed cross-sectional view of a mechanical assembly. The assembly includes a base 1 with a central cavity 5. A vertical shaft 23 passes through the center. Various components are labeled: 1a, 1b, 1c, 2, 4, 5, 6, 11a, 13, 16, 20, 23a, 23b, 26, 31, 32, 41, 42, 51, 52. A downward arrow 5 indicates a direction of movement or force.

*Journal of Management Inquiry* 18(6) 709-724  
© The Author(s) 2009  
Reprints and permissions:  
<http://www.sagepub.com/journalsPermissions.nav>

Fig. 5




Fig. 6 (a)




Fig. 6 (b)




Fig. 6 (c)

